PARTS DEPARTMENT BULLETIN

DATE: 24 November 2008

BULLETIN NUMBER:

2008-4

TO:

All Westerbeke/Universal Distributors and Dealers

SUBJECT:

Aerosol Paint Can Storage

Issues have been reported from the field concerning aerosol paint spray cans not functioning after being sold and customers attempting to use them. The cans will not spray any paint.

Cans returned have been examined by our supplier and it was found that improper storage has been the cause of the spray cans malfunctioning.

The aerosol cans MUST be stored in an UPRIGHT position. Failure to store them in this position will cause the discharge tube on the inside of the can to become blocked making the can inoperable.

Check the storage position of all cans in stock/inventory and advise customers of this storage issue.

The label on these aerosol paint spray cans will be revised to indicate the proper storage position.